

CONVERSION OF INCHES AND MILLIMETRES

In many “imperial” countries, Inches measurements in conveyor belting are converted and rounded as follows:

IN.	=	MM	IN.	=	MM
10	=	250	1/32	=	1
12	=	300	1/16	=	2
14	=	350	3/32	=	2
16	=	400	1/8	=	3
18	=	450	5/32	=	4
20	=	500	3/16	=	5
24	=	600	1/4	=	6
26	=	650	5/16	=	8
30	=	750	3/8	=	10
36	=	900	1/2	=	13
42	=	1050	5/8	=	16
48	=	1200	3/4	=	20
54	=	1350	1	=	25
60	=	1500			
72	=	1800			
84	=	2100			